



Join the split sides using
cross stitching

The cracks are to be
cut with a swivel knife

I left all the teeth in the drawing
so you can cut out whichever one
you like. Tool the rest using a
small beveler or a modelling
tool.

